| | | | | | | 1600 7 | 2 |
|---|--------------|-----------|---------|--------------------------|----------|--|---------|
| EPA REGION V | | | | | | 1 | |
| | DER / REPORT | PAGE | OF | | | | |
| SITE NAME: | | DATE (| -14-95 | | | | |
| SITE/SPILL NO.: | | | | CONTRACT NO.: | | —————————————————————————————————————— | |
| ON-SCENE COORDINATOR: | | | | RESPONSE MANAGER | | | |
| San Borries | | | | Ken Brak | 3 | | |
| MONITORS: | | | | CONTRACTOR: Ried / Santh | | | |
| WORK AUTHORIZED | | | | WORK ACCOMPLISHED | | | |
| | | | | | | | |
| I continue execution along the | | | | 1- On -going | | | |
| north fence line. | | | | 7 | | | |
| | | | | | | | |
| a. Continue dust supravion of execution | | | | 2 maning | | | |
| | | | | 7 | | | |
| 3. Use excavated material to fill low | | | | 3-0n-anin | ed | | |
| soots on lad fill | | | | | | | |
| | | | | | | | |
| 4. follow up on water quality with | | | | 4. Complete / P. Takacs | | | |
| Bob Moser to see about discherge | | | | | | | |
| of depression area water J | | | | | | | |
| 5- | | | | | | | |
| | | | | | | | |
| | · | | · | | | | |
| OSC SIGNATURE RM/SIGNATURE | | | | OSC SIGNATURE | RM S | SIGNATURI | ₹ |
| Sam Ban Shift | | | | Sign | | | |
| July . Inton | | | | | | | |
| SUPERVISOR CLERK CLEAN-UP TECHNICIAN | | | | | | | |
| foreman | <u></u> | LAB TECHN | | | | | |
| CHEMIST | | (| THER | | OTHER | | |
| EQUIPMENT AND MATERIALS | | | | | | | |
| ITEM | QUANTITY | USED | NOTUSED | ITEM | QUANTITY | USED | NOTUSED |
| 280056 T. kg | 1 | | | H.H. Radios | 4 | | |
| 655B 50 boads | 1 | | | Johnnies | 2 | | |
| Vickup truck | 2 | | | | | | |
| 10150 OFF. Trailer | | | | | | | |
| 10 X40 Strape Trails | 11 | | | | | | |
| For machine | , | | | | | | |
| | | | | | | | |
| AMENDMENTS | | | | | | | |
| | | | | | | | İ |
| OSC SIGNATURE | | | | RM SIGNATURE | | | l |